
Address 47: Sound System Labels: 8T0-035-223-BOM.clb
Control Module Part Number: 8T0 035 223 T HW: 8T0 035 223 C
Component and/or Version: DSP Prem H11 0400
Software Coding: 020101
Work Shop Code: WSC 12336 024 394758
VCID: 3F8B35A7AEFF6EE6A27-806A

2 Faults Found:

00003 - Control Module

014 - Defective

Freeze Frame:

Fault Status: 01101110
Fault Priority: 5
Fault Frequency: 1
Reset counter: 255
Time Indication: 0
Date: 2064.00.00
Time: 00:03:52

Freeze Frame:

Voltage: 14.30 V
Temperature: 181.0°C
Temperature: 45.0°C
Bin. Bits: 00000100
Bin. Bits: 00000000
Bin. Bits: 00000100

02095 - Component Protection Active

000 - -

Freeze Frame:

Fault Status: 01100000
Fault Priority: 4
Fault Frequency: 1
Reset counter: 210
Mileage: 179924 km
Time Indication: 0
Date: 2017.12.30
Time: 16:55:47